: OUTLET WELDMENT ASSEMBLY

Date: User: Previous Run Written By Comment Job Number:

Monday, 28/04/2008 8:13:23 AM

Julie Lecocq

Process Sheet

: CU-DAR001 Dart Helicopters Services Customer

Job Number : 38809 **Estimate Number** : 11839

P.O. Number

: 28/04/2008 S.O. No. : This Issue

Prsht Rev. : NC

First Issue

: //

Type : LARGE FAB ASSY **Part Number**

Due Date

Drawing Name

: D2319

Drawing Number

: D2319 REV B : N/A

Project Number Drawing Revision

Material

: 15/05/2008

Qty: 4 Um:

Each

Checked & Approved By

: Est:

05.03.29

New Issue KJ/JLM

Additional Product



Seq. #:

Machine Or Operation:

Description:

D22913

Heater Tube 4"



Comment: Qty.:

1.0000 Each(s)/Unit Total: 4.0000 Each(s)

Heater Tube 4"

D22913

Qty Part Number

Description 4" Heater Tube

2.0

1 D2288

Heater Support



Comment: Qty.:

1.0000 Each(s)/Unit Total: 4.0000 Each(s)

Heater Support

Pick:

Qty Part Number

Description Batch

D2288

Heater Support

D2293

Heater Tube 6"





4.0000 Each(s)



Heater Tube 6"

Pick: Qty

Part Number Description

6" Heater Tube D2293

4.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1

Comment: LARGE FABRICATION RESOURCE 1

Assemble and Weld as per Dwg D2319



Dart Aerospace Ltd

W/O:			WC	ORK ORDER CHANG	ES				P.	· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PROC	EDURE CHA	NGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									-2	
,				<u> </u>						
					,				÷	
Part No	:	PAR #:	_ Fault Cate	gory:	_ NCR: Y	es N	lo DQ	A :	_ Date: _	
					Q	A: N/0	C Close	d:	Date:	
NCR:		W	ORK ORDI	ER NON-CONFORMA	NCE (N	CR)			1 1 2	1
		Describion of NC			Section B		Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		ın & ate	Secti		Chief Eng	QC Inspector
		٣							1	
									÷	
									·	

NOTE: Date & initial all entries

Date: Monday, 28/04/2008 8:13:23 AM User: Julie Lecocq **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: OUTLET WELDMENT ASSEMBLY** Job Number: 38809 Part Number: D2319 Job Number: Seq. #: **Machine Or Operation:** Description: VISUAL WELDING INSPECTION QC9 5.0 Comment: VISUAL WELDING INSPECTION (4) QC5 INSPECT WORK TO CURRENT STEP 6.0 Comment: INSPECT WORK TO CURRENT STEP 7.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 8.0 QC21 08/07/25 954 MF 08-07-24 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace Ltd

W/O:			WC	ORK ORDER CHANGE	S				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date (Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								P	
Part No) :	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:		Date: _	·
					QA: N	/C Closed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORMAN			-		
DATE	STEP	Description of NC		Corrective Action Section		Verificat	ion	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
								1	
	1.								
								*	

NOTE: Date & initial all entries





	PARED Williams		DART AERO ACCESSORIES VICTORIA INTERNATIONAL AIRPORT, CANADA	INC
CHEC		APPROVED		REV. B
13	(S)	4	D2319 SHEET	1 OF 2
DATE			TITLE	SCALE
Jar	ı. 10, 1	995	OUTLET WELDMENT ASSEMBLY	
В		96:04:18	MODIFIED MASTER PARTS LIST	

QTY	Part No.	Description
X	D2319	OUTLET WELDMENT ASSEMBLY
1	D2291-3	4" RING
1	D2293	6" RING
1	D2288	END PLATE

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 3





PREPARED		DART AERO ACCESSOR	IEC INC
B. William	ns ,	VICTORIA INTERNATIONAL AIRPORT.	MANADA
CHECKED	ARPROVED		REV. 8
BW		D2319	SHEET 2 OF 2
DATE		TITLE	SCALE
Jan 10	1005	OUT ET WEI DUENT ACCENCIA	

